


REPORT OF THE SEISMIC TESTS CARRIED OUT ON
“TWO (2) ACCELEROGRAPHS”
SUPPLIED BY SEISODIN



Documents and activities marked with (*), as well as information and activities indicated as supplied or performed by the client, are not covered by ENAC accreditation

NOTE: According to section 7.8.2 of standard ISO-IEC 17025:2017, it is stated that:

- The results of the present report apply only and exclusively to the samples subjected to test.
- The partial reproduction of this document without the previous written permission of the Laboratory is forbidden.
- The Laboratory is not responsible for the information and activities indicated as supplied or performed by the client.

VIRLAB, S.A.
Division of URBAR INGENIEROS, S.A.

Polígono Industrial de Asteasu
Zona B, Pabellón 44
20159 Asteasu (Guipúzcoa)
SPAIN

www.virlab.es
E-mail: laboratorio@virlab.es
Tel.: +34 943 69 15 00

Carried out by

Firmado digitalmente por Tristan Ugarte
Fecha: 2024.04.12 13:29:40 +02'00'

Laboratory Engineer

Revised and authorized by

Firmado digitalmente por Alberto CORRAL
Fecha: 2024.04.12 13:43:49 +02'00'

Technical Director